

SECRET**PRIORITY**

OUT60564

M

P 032114Z DEC 66
 FM NPIC WASHDC
 TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
 RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
 RUCVAAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 9228.

1966 DEC 3 21 32Z

5 DEC 1966

Of To	Office	Action
1	SEC BR	
2	TOS	
3	OSD	
4	IPD	
5	PD	
6	PSD	
7	PSD/CE	
8	TIG	
9	IAD	
10	PRG	
11	DIAAX-5	
12	SPAD	
13	NSA-L3	
14	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
 2D AF (FOR DI).

1. CAMERA B 15 WAS USED IN MISSION G 930 FLOWN ON 30
 NOVEMBER 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE

A. THE DENSITY AND RESOLUTION WERE GOOD. HOWEVER,
 THE RESOLUTION OF THE 1R AND 1L POSITION IN SOME INSTANCES
 IS NOT COMPARABLE TO THE BEST RECEIVED IN OTHER 1R AND 1L
 POSITIONS.

B. 9R SIDE: EDGE STATIC AND ROLLER CHATTER IS PRESENT
 ON BOTH EDGES OF THE FILM. THERE ARE TWO ROWS OF MINUS
 DENSITY DOTS 1.7" APART LOCATED 1.0" FROM THE INBOARD
 EDGE AND 1.7" FROM THE OUTBOARD EDGE. THEY ARE PRESENT
 THROUGHOUT THE MISSION. HEAT SPLICES ARE BETWEEN FRAMES
 299/300 AND 599/600. AN ULTRASONIC SPLICE IS BETWEEN
 FRAMES 1801/1802. MANUFACTURING SPLICES ARE LOCATED IN
 FRAMES 1293 AND 2118. THEY ARE BOTH ACCOMPANIED BY THE
 NORMAL FOG PATTERN.

Declassification Review by
NGA/DoD**SECRET**

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

- 2 -

C. 9L SIDE: EDGE STATIC WAS NOTED ALONG BOTH EDGES OF THE FILM THROUGHOUT THE MISSION. MANUFACTURING SPLICES ARE LOCATED IN FRAMES 60 AND 679. THEY ARE ACCOMPANIED BY THE USUAL FOG. THERE IS A SPLICE BETWEEN FRAMES 299 AND 300.

D. BOTH SIDES: A FEW FRAMES WERE NOTED TO BE SMEARED. THIS IS PROBABLY CAUSED BY THE ROLL OF THE VEHICLE. THERE IS A CHANGE IN DENSITY NOTED IN SOME OF THE VERTICAL FRAMES. THIS IS THOUGHT TO BE AN INTERNAL CAMERA REFLECTION AND IT HAS BEEN REPORTED BEFORE. THE LAST TITLED FRAME IS 2393.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 15 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-